



Preliminary Environmental Information Report: Annex 5.5 – Screening Assessment – Onshore HVAC Booster Station

Date: July 2017





Hornsea Project Three

Offshore Wind Farm



Environmental Impact Assessment

Preliminary Environmental Information Report

Volume 6

Annex 5.5 – Screening Assessment – Onshore HVAC Booster Station

Liability

This report has been prepared by RPS, with all reasonable skill, care and diligence within the terms of their contracts with DONG Energy Power (UK) Ltd.

Report Number: P6.6.5.5

Version: Final

Date: July 2017

This report is also downloadable from the Hornsea Project Three offshore wind farm website at: www.dongenergy.co.uk/hornsea-project-three-development

DONG Energy Power (UK) Ltd. 5 Howick Place, Prepared by: RPS London, SW1P 1WG Checked by: Jennifer Brack © DONG Energy Power (UK) Ltd. 2017. All rights reserved. Accepted by: Jennifer Brack Front cover picture: Kite surfer near one of DONG Energy's UK offshore wind farms © DONG Energy Hornsea Approved by: Stuart Livesey Project Three (UK) Ltd., 2016.







Table of Contents

1.	Scre	eening Assessment – Onshore HVAC Booster Station	.1
1.	.1	Introduction	.1

List of Tables

Table 1.1:	Scheduled Monuments Screening Assessment.	2
	Listed Buildings Screening Assessment	
	Registered Parks and Gardens Screening Assessment.	
	Conservation Area Screening Assessment.	

List of Figures

Figure 1:	Listed buildings, registered parks and gardens and scheduled monuments within 10 km buffer of the	
	onshore HVAC booster station1	2

Summary

This annex provides a screening assessment of designated heritage assets of the highest significance (Grade I and II* listed buildings and Scheduled Monuments) within a 10 km radius of the onshore HVAC booster station and other heritage assets (Grade II listed buildings and Conservation Area) within a 5 km radius to determine whether they might be potentially affected by the development. Where it is concluded there is a potential for significant effects, the potential effects on those assets has been assessed in volume 6, chapter 5: Historic Environment.

Acronyms


Acronyms	Description
LVIA	Landscape and Visual Impact Assessment
ZTV	Zone of Theoretical Visibility

Units

Unit	Description
km	Kilometre (length)
m	Metre (length)









Screening Assessment – Onshore HVAC Booster Station 1.

1.1 Introduction

- 1.1.1.1 The tables below provide the screening assessment based primarily on information on designated assets obtained to inform the Hornsea Three onshore baseline.
- 1.1.1.2 In accordance with the scoping report and scoping opinion, potential temporary and permanent impacts on the setting of designated heritage assets of the highest significance (Grade I and II* listed buildings and Scheduled Monuments) are assessed within a 10 km radius of the onshore HVAC booster station presented in section 5.3 of volume 3, chapter 5: Historic Environment. In addition potential temporary and permanent impacts on the setting of other designated heritage assets (e.g. Grade II listed buildings and Conservation Areas) are assessed within a 5 km radius of the onshore HVAC booster station.
- 1.1.1.3 In the first instance this screening assessment has been undertaken in order further to understand those assets where it was unlikely that significant effects would be created by Hornsea Three. The screening assessment used a Zone of Theoretical Visibility (ZTV), similar to that generated for the Landscape and Visual Impact Assessment (LVIA). The ZTV used for this assessment models terrain and land-cover, the latter using indicative heights. These heights are 12 m for woodland and 9 m for buildings. The methodology for the ZTV process is set out in appendix B of volume 6, annex 4.1: Landscape and Visual Assessment Methodology.
- 1.1.1.4 Those assets located entirely outside the ZTV have been screened out as have those where distance, orientation (where appropriate) and the small areas of those large assets lying within the ZTV indicate that there would be no significant effects created by Hornsea Three.
- 1.1.1.5 Figure 1 at the end of this document shows the locations of the assets listed in Table 1.1 to Table 1.4 below.





Table 1.1: Scheduled Monuments Screening Assessment.

List Entry Number	Name	Notes
1003165	Habitation site on Edgefield Heath	Outside ZTV - no further assessment
1003167	St Margaret's Church, Wolterton	Outside ZTV - no further assessment
1003903	Moated site South of Bessingham Wood	Outside ZTV - no further assessment
1004022	Gresham Castle	Outside ZTV - no further assessment
1013093	Baconsthorpe Castle moated site with fortified house, gatehouse, courtyards and formal gardens	Outside ZTV - no further assessment
1013096	Weybourne priory	Outside ZTV - no further assessment
1013097	Moated site 380 m SSW of Rosedale Farm	Outside ZTV - no further assessment
1013559	Bowl barrow in Taylors Wood, 400 m north of Swan Lodge: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013560	Bowl barrow in Taylors Wood, 270 m north east of Swan Lodge: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013561	Bowl barrow in Taylors Wood, 350 m north east of Swan Lodge: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013562	Two bowl barrows in Taylors Wood, 260 m north east of Swan Lodge: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013564	Gallow Hill bowl barrow and adjacent group of eight bowl barrows: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013565	Bowl barrow known as Three Halfpenny Hill: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013566	Bowl barrow known as Three Farthing Hill: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013567	Oval barrow in Bodham Wood, 600 m ESE of Warren Farm	Outside ZTV - no further assessment
1013568	Oval barrow with superimposed bowl barrow known as Howe's Hill, 500 m WSW of Wood Farm	Outside ZTV - no further assessment
1013577	Bowl barrow 260 m NNW of Lowes Farm: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013578	Bowl barrow 450 m north west of Lowes Farm: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013579	Bowl barrow 400 m east of Swan Lodge: part of a dispersed round barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013581	Bowl barrow and adjacent group of seven small barrows 550 m NNE of Swan Lodge: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013582	Saucer barrow and adjacent small bowl barrow 630 m north east of Swan Lodge: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment







	-	-
List Entry Number	Name	Notes
1013583	Small bowl barrow 750 m north east of Swan Lodge: part of a barrow cemetery on and around Salthouse Heath	Outside ZTV - no further assessment
1013584	Bowl barrow on the north side of Muckleburgh Hill	Outside ZTV - no further assessment
1013585	Bowl barrow on Kelling Heath, south of Holgate Hill	Outside ZTV - no further assessment
1013586	Bowl barrow in Hundred Acre Wood, 330 m west of Cherry Trees Farm	Outside ZTV - no further assessment
1015253	Sharrington village cross	Outside ZTV - no further assessment
1017672	Castle Hill medieval ringwork, Hunworth	Outside ZTV - no further assessment
1018299	Wayside cross 650 m south west of Park Farm	Outside ZTV - no further assessment
1018676	Wayside cross at Page's Farm	Significant screening is provided by vegetation and buildings and there would be few if any views of the onsho

Table 1.2: Listed Buildings Screening Assessment.

List Entry Number/Name	Grade	Notes	
Grade I Listed Buildings within 10 km of onshore HVAC booster station			
1049221 - Church Of St Peter	1	Within Melton Constable Hall Conservation Area	
1049393 - Church Of St Andrew	1	Outside ZTV - no further assessment	
1049422 - Church Of St Maurice	1	Outside ZTV - no further assessment	
1049800 - Church Of All Saints	1	Outside ZTV - no further assessment	
1049802 - Ruins Of Augustinian Priory	1	Outside ZTV - no further assessment	
1049845 - Remains Of Baconsthorpe Castle	1	Outside ZTV - no further assessment	
1049863 - Hanworth Hall	1	Outside ZTV - no further assessment	
1049875 - Wolterton Hall	1	Outside ZTV - no further assessment	
1050830 - The Old Hall	1	Outside ZTV - no further assessment	
1050963 - Church Of St Peter	1	Further assessed in Chapter	
1051428 - Blickling Hall	1	Outside ZTV - no further assessment	
1051429 - Service Range To South East Of Blickling Hall	1	Outside ZTV - no further assessment	
1051583 - Parish Church Of Saint Michael Including Church Yard Boundary Wall	1	Within Aylesham Conservation Area and assesse	
1076872 - Church Of The Nativity Of St Mary With Brick Retaining Wall To The North	1	Outside ZTV - no further assessment	
1153044 - Melton Constable Hall	1	Outside ZTV - no further assessment	
1172116 - Church Of St Andrew	1	Further assessed in Chapter	
1172181 - Church Of St Mary	1	Further assessed in Chapter	



hore HVAC booster station - no further assessment

a and assessed with that asset
sed with that asset



List Entry Number/Name	Grade	Notes
1263465 - The Parish Church Of St Agnes	1	Outside ZTV - no further assessment
1304544 - Church Of St Mary	1	Outside ZTV - no further assessment
1304622 - Mannington Hall	1	Outside ZTV - no further assessment
1305337 - Church Of St Peter And St Paul	1	Outside ZTV - no further assessment
1305969 - Church Of All Saints	1	Outside ZTV - no further assessment
1306145 - Church Of Saints Peter And Paul	1	Further assessed in Chapter
1372691 - Service Range To South West Of Blickling Hall	1	Outside ZTV - no further assessment
1372695 - Heydon Hall	1	Outside ZTV - no further assessment
1373464 - Church Of St Andrew	1	Outside ZTV - no further assessment
1373472 - Church Of All Saints (Redundant)	1	Outside ZTV - no further assessment
1373644 - Felbrigg Hall	1	Outside ZTV - no further assessment
1373792 - Barningham Hall	1	Outside ZTV - no further assessment
1373804 - Church Of St Andrew	1	Outside ZTV - no further assessment
Grade II* Listed Buildings within 10 km of onshore HVAC booster station		
1049179 - Coach House And Stables To Barningham Hall	*	Outside ZTV - no further assessment
1049180 - Church Of St Mary Barningham Winter	*	Outside ZTV - no further assessment
1049184 - Church Of St Peter	*	Outside ZTV - no further assessment
1049189 - Church Of St Lawrence	*	Outside ZTV - no further assessment
1049191 - Hunworth Mill And Attached Millhouse	*	Outside ZTV - no further assessment
1049195 - Dovecote, c. 30 m South East Of Thornage Hall	*	Outside ZTV - no further assessment
1049202 - Church Of St Peter	*	Further assessed in Chapter
1049203 - Remains Of Former Parish Church Of St Peter And St Paul	*	Outside ZTV - no further assessment
1049204 - Church Of St Peter And St Paul	*	Outside ZTV - no further assessment
1049211 - Church Of All Saints	*	Outside ZTV - no further assessment
1049215 - Remains Of Parish Church Of Mannington	*	Outside ZTV - no further assessment
1049239 - Church Of All Saints	*	Outside ZTV - no further assessment
1049316 - The Old Rectory	*	Outside ZTV - no further assessment
1049430 - Sharrington Hall	*	Outside ZTV - no further assessment
1049496 - Church Of St Andrew	*	Outside ZTV - no further assessment



	_



List Entry Number/Name	Grade	Notes
1049519 - Cross	*	Outside ZTV - no further assessment
1049799 - Sheringham Hall	*	Outside ZTV - no further assessment
1049826 - Thornfield Residential Home For The Elderly	*	Outside ZTV - no further assessment
1049831 - Hall Farmhouse	*	Outside ZTV - no further assessment
1049832 - Letheringsett Hall	*	Outside ZTV - no further assessment
1049834 - Church Of St Andrew	*	Outside ZTV - no further assessment
1049838 - The Mill	*	Outside ZTV - no further assessment
1049847 - Church Of St Mary	*	Outside ZTV - no further assessment
1049848 - The Manor House	*	Outside ZTV - no further assessment
1049862 - Church Of St Bartholomew	*	Further assessed in Chapter
1049885 - Church Of St Ethelbert	*	Further assessed in Chapter
1049886 - Church Of All Saints	*	Within Mannington and Wolterton Conservation A
1049900 - Church Of St Margaret	*	Outside ZTV - no further assessment
1050949 - Bank Cottage And Oak House	*	Further assessed in Chapter
1051432 - The Doric Temple	*	Outside ZTV - no further assessment
1051437 - The Mausoleum	*	Within Blickling Conservation Area and assessed
1051551 - Old Bank House	*	Outside ZTV - no further assessment
1051567 - Knoll House	*	Outside ZTV - no further assessment
1076855 - Manor House	*	Outside ZTV - no further assessment
1151974 - Kelling Hall	*	Outside ZTV - no further assessment
1152001 - The Stables, Wolterton Hall	*	Outside ZTV - no further assessment
1152481 - Church Of All Saints	*	Outside ZTV - no further assessment
1152734 - Manor Farm House And Attached Garden Walls	*	Outside ZTV - no further assessment
1152882 - Church Of St Michael	*	Further assessed in Chapter
1152886 - Hope House	*	Further assessed in Chapter
1153034 - Thornage Water Mill	*	Outside ZTV - no further assessment
1153202 - Church Of St Andrew	*	Further assessed in Chapter
1169735 - Old Hall	*	Outside ZTV - no further assessment
1170353 - Salle Park	*	Further assessed in Chapter
1170402 - Yew Tree House Including Boundary Wall	*	Within Aylesham Conservation Area and assesse
1170582 - Briningham House	*	Outside ZTV - no further assessment



Area and assessed wih that asset
ed wih that asset
sed wih that asset





List Entry Number/Name	Grade	Notes
1171857 - Church Of St Andrew	*	Outside ZTV - no further assessment
1172066 - Congregational Chapel	*	Outside ZTV - no further assessment
1172366 - Church Of All Saints	*	Outside ZTV - no further assessment
1172575 - Church Of St Lawrence	*	Outside ZTV - no further assessment
1304415 - Church Of St Edmund	*	Outside ZTV - no further assessment
1304519 - Thornage Hall	*	Outside ZTV - no further assessment
1304991 - Church Of St Margaret	*	Outside ZTV - no further assessment
1305293 - Wood Dalling Hall	*	Further assessed in Chapter
1305348 - Outbuilding And Adjoining Walls To North, South And East At Hall Farm	II*	Outside ZTV - no further assessment
1305357 - Cropton Hall	*	Within Hedon and Salle Conservation Area and a
1305371 - Church Of St Mary	*	Within Bessingham Conservation Area and asses
1305393 - Church Of St Peter And St Paul	*	Outside ZTV - no further assessment
1305530 - Church Of All Saints	II*	Outside ZTV - no further assessment
1305722 - Church Of St Mary	*	Outside ZTV - no further assessment
1306488 - Church Of St Michael And All Angels	*	Outside ZTV - no further assessment
1306557 - Parish Church Of St Andrew	*	Outside ZTV - no further assessment
1342799 - Moor Hall	*	Further assessed in Chapter
1372668 - The Manor House	*	Outside ZTV - no further assessment
1372723 - Church Of St Peter And St Paul	*	Outside ZTV - no further assessment
1372914 - Congregational Chapel	*	Further assessed in Chapter
1373470 - Church Of St Mary	*	Outside ZTV - no further assessment
1373476 - Church Of St Mary	*	Outside ZTV - no further assessment
1373639 - Church Of St John Baptist	*	Outside ZTV - no further assessment
1373647 - Church Of St Peter	*	Further assessed in Chapter
1373774 - Melton Constable Hall North Wing And Stable Court South Wing	*	Outside ZTV - no further assessment
1373807 - Church Of St Mary	*	Outside ZTV - no further assessment
1373811 - The Bath House	*	Outside ZTV - no further assessment
1373820 - Church Of All Saints	*	Outside ZTV - no further assessment
1373831 - Church Of St Andrew	*	Within Mannington and Wolterton Conservation A



assessed wih that asset
essed wih that asset
Area and assessed with that asset





List Entry Number/Name	Grade	Notes
Grade II* Listed Buildings within 5 km of onshore HVAC booster station		
1049157 - Coffin Lid About 15 m North Of Church Of St Mary The Virgin	II	Outside ZTV - no further assessment
1049174 - Walls To Garden And Moat, Bridge And Attached Gazebo And Arch At Mannington Hall		Outside ZTV - no further assessment
1049175 - Temple In Garden Of Mannington Hall c. 50 m South Of South East Corner Of Moat	II	Outside ZTV - no further assessment
1049176 - Barningham Lowes	II	Further assessed in Chapter
1049177 - Ferndale Farmhouse		Outside ZTV - no further assessment
1049178 - Barn At Ferndale Farm		Outside ZTV - no further assessment
1049181 - Garibaldi Cottage	II	Outside ZTV - no further assessment
1049182 - Old Rectory	II	Outside ZTV - no further assessment
1049183 - Barn At Hall Farm		Outside ZTV - no further assessment
1049185 - South Lodge To Barningham Hall		Outside ZTV - no further assessment
1049186 - Barn At Hall Farm		Outside ZTV - no further assessment
1049187 - 30 And 31, Church Street		Further assessed in Chapter
1049188 - Walnut Farm House		Further assessed in Chapter
1049192 - The Firs	II	Outside ZTV - no further assessment
1049201 - Watermill And Attached Mill House		Outside ZTV - no further assessment
1049205 - Church Farm House		Further assessed in Chapter
1049206 - Edgefield Hall	II	Outside ZTV - no further assessment
1049207 - Lowes Farm House		Outside ZTV - no further assessment
1049208 - The Mount		Outside ZTV - no further assessment
1049209 - 3 And 4, Holt Road	II	Further assessed in Chapter
1049210 - Barn At Langer Farm		Outside ZTV - no further assessment
1049212 - Barn At Green Farm 50 m North West Of Green Farm House		Outside ZTV - no further assessment
1049213 – Brownwood	II	Outside ZTV - no further assessment
1049214 - Hill Farmhouse		Outside ZTV - no further assessment
1049216 - Arch 12 m South East Of Chancel Of Mannington Church		Outside ZTV - no further assessment
1049241 - Hall Farmhouse		Outside ZTV - no further assessment
1049243 - The Lawn		Outside ZTV - no further assessment
1049841 - Estate Yard Cottage Woodyard Cottage	II	Outside ZTV - no further assessment
1049844 - Cartshed And Granary About 50 m South West Of Hall Farmhouse		Further assessed in Chapter







List Entry Number/Name	Grade	Notes
1049846 - Remains Of Baconsthorpe Hall c. 80 m South Of Baconsthorpe Castle	П	Outside ZTV - no further assessment
1049849 - Right Gate Pier To Manor House And Attached Splayed Garden Wall	П	Outside ZTV - no further assessment
1049850 - The Old School	П	Outside ZTV - no further assessment
1049874 - Barn At Hall Farm, Mannington	П	Further assessed in Chapter
1049880 - Dairy Cottages	П	Outside ZTV - no further assessment
1068822 - Granary Immediately East Of Limetree Farmhouse	П	Further assessed in Chapter
1068844 - Manse	П	Outside ZTV - no further assessment
1152661 - Merrisons Farm House 150 m North West Of Parish Church Of St Peter And St Paul	11	Further assessed in Chapter
1152703 - Langer Farm House	11	Outside ZTV - no further assessment
1152709 - Old Hall Farmhouse	11	Outside ZTV - no further assessment
1152711 - Barn c. 50 m North West Of Old Parsonage House	Ш	Further assessed in Chapter
1152715 - Green Farm House	Ш	Outside ZTV - no further assessment
1152720 - Hempstead Hall	11	Outside ZTV - no further assessment
1152729 - Memorial To John Fish 4 m South Of Chancel Of Church Of St Mary The Virgin	11	Outside ZTV - no further assessment
1152757 - Arch c. 9 m South West Of Nave Of Mannington Church	Ш	Outside ZTV - no further assessment
1152804 - The Lawn Barn	П	Outside ZTV - no further assessment
1152835 - Vases And Steps c. 10 m East Of Barningham Hall	11	Outside ZTV - no further assessment
1152844 - Gatepiers And Overthrow At Church Of St Mary Barningham Winter	П	Outside ZTV - no further assessment
1152857 - Dairy Farmhouse	П	Outside ZTV - no further assessment
1152880 - Jubilee Cottage	П	Outside ZTV - no further assessment
1152888 - Church Farm House	П	Further assessed in Chapter
1152893 - Plumstead Hall	П	Further assessed in Chapter
1152936 - Green Farm House	П	Outside ZTV - no further assessment
1153218 - Rookery Farm House	П	Outside ZTV - no further assessment
1172082 - Irmingland Hall	П	Outside ZTV - no further assessment
1240102 - Barn Immediately East Of Limetree Farmhouse	П	Further assessed in Chapter
1240835 - Dairy Cottages	П	Outside ZTV - no further assessment
1240885 - Dairy Cottages	П	Outside ZTV - no further assessment
1253197 - The Old Rectory And Attached Walls And Stable Block	11	Outside ZTV - no further assessment
1304551 - Hall Farm Cottage	П	Outside ZTV - no further assessment
1304554 - 18 And 19, The Street	11	Outside ZTV - no further assessment
	1	







List Entry Number/Name	Grade	Notes
1304570 - Piers Gates And West Wall To Courty Yard At Baningham Hall	П	Outside ZTV - no further assessment
1304607 - Summer House 250 m North East Of Manor Farmhouse	П	Further assessed in Chapter
1304637 - Hole Farm House	Ш	Outside ZTV - no further assessment
1304649 - 1 And 2, Holt Road	Ш	Further assessed in Chapter
1305000 - Hall Farm House, Mannington	Ш	Further assessed in Chapter
1373484 - Farmbuildings Immediately West North West Of Park Farmhouse	Ш	Outside ZTV - no further assessment
1373486 - Barn At Hall Farm c. 35 m West Of Baconsthorpe Hall	11	Outside ZTV - no further assessment
1373487 - Manor House Farmhouse	11	Further assessed in Chapter
1373488 - Left Gate Pier To Manor House And Attached Splayed Garden Wall	11	Outside ZTV - no further assessment
1373489 - The White House	11	Outside ZTV - no further assessment
1373778 - Rookery Farm Cottages	11	Outside ZTV - no further assessment
1373783 - Roper Farmhouse	Ш	Outside ZTV - no further assessment
1373793 - Kitchen Garden Wall c. 40 m North East Of Barningham Hall	Ш	Outside ZTV - no further assessment
1373794 - Cromer Lodge	Ш	Outside ZTV - no further assessment
1373796 - Dickers	Ш	Outside ZTV - no further assessment
1373802 - Little London Farm House	Ш	Outside ZTV - no further assessment
1373803 - Manor House	Ш	Outside ZTV - no further assessment
1373805 - Old Parsonage House	11	Further assessed in Chapter
1373808 - Old Rectory	Ш	Outside ZTV - no further assessment
1373823 - Two Piers Of Cottages Coach House And Adjacent Range To West, Immediately North West Of Mannington Hall	Ш	Outside ZTV - no further assessment
1373829 - Draw Bridge At Mannington Hall	Ш	Outside ZTV - no further assessment
1373830 - Mere Farm House	11	Outside ZTV - no further assessment

Table 1.3: Registered Parks and Gardens Screening Assessment.

List Entry Number	Name	Grade	Notes
1000154	BLICKLING HALL	*	Significant screening is provided by vegetation and buildings and there would be few if any vi assessment
1000185	FELBRIGG HALL	11*	Significant screening is provided by vegetation and buildings and there would be few if any vi assessment



Annex 5.5 – Screening Assessment – Onshore HVAC Booster Station Preliminary Environmental Information Report July 2017

y views of the onshore HVAC booster station - no further

y views of the onshore HVAC booster station - no further





List Entry Number	Name	Grade	Notes
1000187	HEYDON HALL	*	Significant screening is provided by vegetation and buildings and there would be few if any vi assessment
1000533	MELTON CONSTABLE HALL	*	Significant screening is provided by vegetation and buildings and there would be few if any vierassessment
1001002	Barningham Hall	II	Significant screening is provided by vegetation and buildings and there would be few if any vi assessment
1001009	Mannington Hall	11	Significant screening is provided by vegetation and buildings and there would be few if any vi assessment
1001016	Salle Park	11	Further assessed in chapter
1001020	Sheringham Hall	11*	Outside ZTV - no further assessment
1001022	Wolterton Hall	*	Significant screening is provided by vegetation and buildings and there would be few if any vir assessment
1001428	Voewood	*	Outside ZTV - no further assessment

Table 1.4: Conservation Area Screening Assessment.

Name	Notes
Aldborough	Outside ZTV - no further assessment
Aylsham	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Baconsthorpe	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Bessingham (Sustead)	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Blickling	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Brinton and Thornage	Outside ZTV - no further assessment
Cawston	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Edgefield	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Glaven Valley	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Gunthorpe	Outside ZTV - no further assessment
Gunton Park	Outside ZTV - no further assessment
Hanworth	Outside ZTV - no further assessment
Hempstead	Outside ZTV - no further assessment
Heydon	Outside ZTV - no further assessment
Heydon and Salle	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment



Annex 5.5 – Screening Assessment – Onshore HVAC Booster Station Preliminary Environmental Information Report July 2017

views of the onshore HVAC booster station - no further

views of the onshore HVAC booster station - no further

views of the onshore HVAC booster station - no further

views of the onshore HVAC booster station - no further


views of the onshore HVAC booster station - no further





Name	Notes
Holt	Outside ZTV - no further assessment
Hunworth (Stody)	Outside ZTV - no further assessment
Ingworth	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Itteringham	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Kelling	Outside ZTV - no further assessment
Letheringsett	Outside ZTV - no further assessment
Mannington and Wolterton	Further assessed in chapter
Matlaske	Outside ZTV - no further assessment
Melton Constable	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Melton Constable Park	Significant screening is provided by vegetation and buildings and there would be few if any views of the onshore HVAC booster station - no further assessment
Reepham	Outside ZTV - no further assessment
Sharrington	Outside ZTV - no further assessment
Upper Sheringham	Outside ZTV - no further assessment
Weybourne	Outside ZTV - no further assessment





Listed buildings, registered parks and gardens and scheduled monuments within 10 km buffer of the onshore HVAC booster station. Figure 1:

	Onsho	ore HVAC booster Buffer	station locatior	ו		
	10km	10km Buffer				
	nonacciant and a second second	Within a buffer of 5km				
	Grade					
		tered Park and Ga	rden (Grade II)		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	uffer of 10km				
	Crade III listed building					
040000		tered Park and Ga	rden (Grade I.	ዴ ॥*ነ		
540	100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100	uled Ancient Mon		ωπ)		
		ervation area	ament			
		ervation area				
3						
222000						
Ó						
3						
200						
ń						
	57.0					
	Reference System : OSGB36 Scale@A3:1:120,000 Projection : BNG Vertical reference: Newlyn					
	0	2	4 Kilometres			
			TO MARK TO MARK A STOCK			
		n				
Ş	REV	REMARK			DATE	
222000	00	Initial Issue			01/07/17	
20						
		Hornsea F	Project Thre	ee		
		Screening Onshore HVA	Assessment	-		
		Onshore HVA	C booster st	ation		
	Created by: MS	Doc no: RPS-9337-0311-02 Created by: MS				
	Checked by: C Approved by:S		RPS	ener		

